

□1□Product Model□Version□

□2□Description of the problem

Which ports were used and how it generally chooses ports when connecting XVR via P2P connection□

□3□Problem Processing (Root Cause)

□4□Solution

P2PServer: 8800, 8802, 8803 UDP, 8801 TCP --- Device registration P2PRelay: 0 ~ 65535
UDP, 8901 TCP --- P2P forwarding transmission ASPlus: 12366, 12367 TCP --- Device port
reporting
DNS: 53 UDP --- Domain name resolution